	AUTOMOTIVE ALLOWANCE		
	Preliminary Maintenance		
	Diagnose / adjust brakes		
	Re-pack Bearings		
	Install Break-Away Switch w/ Battery		
	Repair running lights / signals	_	
	Labor: Estimated 3-4 hrs.	\$	475.00
	Materials	\$	97.50
	Tax	\$	49.86
	General Maintenance Hardware, Tools & Materials		
	Original 1970 Factory Airstream Service Manual	\$	63.98
	Airstream Life's (Nearly) Complete Guide to Airstream Maintenance	\$	26.99
	7-Way Trailer Plug: Burnishing Tool & DeOxIT	\$	16.84
	One (1) Stanley MR100CG Contractor Grade Riveter	\$	19.99
	5052 Aluminum Open End Blind Rivet with Aluminum Break Pull		
	Mandrel, Meets IFI-114 Grade 11, Countersunk Head, 1/8" Diameter,		
	0.275" Length, 0.063"-0.125" Grip Range (Pack of 250)	\$	13.28
	Rust-Penetrating Oil	\$	5.96
	Lock Ease Fluid	\$	3.57
	One (1) Metal Brake Safety Switch	\$	31.08
	Avia / Shock Banjacament		
	Axle / Shock Replacement Two (2) new Torsion Axles	\$	1,290.00
	Four (4) new Monroe Gas Magnum shocks (#555003)	\$	64.00
	Shipping		NCLUDED
	Labor (6 hours)	\$	450.00
	Tax	\$	144.32
	Running Gear		
	Rebuild brakes [New brake assembly comes with new axles, above]	Ш	NCLUDED
	140		
	Wheels Parkers four (4) tires: Pood Piercer 7 00 15LT. F. Treed	æ	500.60
	Replace four (4) tires: Road Pioneer 7.00-15LT, E Tread Four (4) High-Pressure Tire Stems	\$	509.68 NCLUDED
	roul (4) High-Fressure file Stellis	"	NCLODED
	Towing		
	Reese Hitch Ball	\$	13.99
	Two (2) Clips connecting Chains to Tow Vehicle	\$	5.50
	Brake Controller		
	Tekonsha 90885 Prodigy P2 Electronic Brake Control + Tekonsha 3040-	_	
	P Brake Control Wiring Adapter (for Toyota Tacoma)	\$	120.95
	Installation	\$	154.79
	Parking Equipment		
	Brahma Wheel Lock	\$	298.00
	Four (4) Stabilizing Jacks		DONATED
	Four (4) Tire Covers	\$	29.84
	,	-	
	NOTE: See Alternates #1 below to include Segment Protectors		
		_	
	Automotive Allowance Tota	I_\$	3,885.13
	CONSERVATION TREATMENT FOR EXISTING REDIOD		
020300-	STRUCTURES		
020000	Exterior		
	Lubricate hardware (Hitch Coupler, &c.)		N/C
	Wash trailer		N/C
	Five (5) Tubes Aluminum Pigmented Gutterseal	[	DONATED
	To remove surface rush & polish four (4) Baby Moon hubcaps (Materials		
	Only)	\$	27.95
	Interior (Throughout)		
	Interior (Throughout) Lubricate hardware (locks, latches, hinges, &c.)		N/C
	Lubricate riardware (locks, lateries, filliges, &c.)		14/0
	Dinette		
	To reinstall one (1) Window Striker Plate		C/O
	• •		
	Galley		
	To remove, clean & reinstall two (2) Sink Strainers		DIY
	To clean and replace refrigerator accessories		DIY
	Conservation Treatment for Existing Period Structures Tota	•	27 05
	Conservation freatment for Existing Period Structures Tota	ıĮΦ	27.95

024100-	DEMOLITION Disposal of Airstream Safari cushions Recycling Airstream Safari Dinette cushion	\$	5.00 5.00
	Recycling Airstream Trade Wind cushions  Demolition Total		10.00
024200-	REMOVAL AND SALVAGE OF CONSTRUCTION MATERIALS Parts Trailer Purchase 1969 Airstream Safari (Bearings check included) Cleaning Supplies Parking Costs	\$ \$ \$	1,299.00 59.71 1,800.00
	Entry Door To remove Entry door from Parts Trailer & swap w/ Trade Wind		
	<u>Compartment Doors</u> Swap out Compartment Door on Curb Side		N/C
	Windows Throughout To remove eight (8) Window Pulls from Parts Trailer & reinstall in Trade Wind		N/C
	<u>Curbside Front Window / Kitchen Window</u> To remove three (3) Lower Latch Assemblies from Parts Trailer & reinstall in Trade Wind		N/C
	Front Vent Cover To remove front vent cover from Parts Trailer & cover with plastic		N/C
	<u>Galley Light Fixture</u> To remove one (1) Sink Light for installation in Trade Wind		N/C
	Removal and Salvage of Construction Materials Total	\$	3,158.71
051200-	STRUCTURAL METAL FRAMING		
001200	Tongue & Front Chassis Repair Repair by welding new material	\$	1,730.28
	Materials Primer & Paint	\$	61.06
	Structural Metal Framing Tota	\$	1,791.34
	METAL STAIRS		
	Install Replacement Safety Tread	\$	6.23
	Metal Stairs Total	\$	6.23
064000-	ARCHITECTURAL WOODWORK		
	<u>Dinette</u> To clean, sand and re-finish wood cushion backs (Labor Only)		DIY
	Throughout To sand and varnish Cabinet Doors (Labor Only)		DIY
	Materials Tried & True Varnish Oil	\$	33.87
	Architectural Woodwork Tota	\$	33.87
070000-	THERMAL AND MOISTURE PROTECTION ALLOWANCE		
	Materials Three (3) tubes of Eco-Bond Clear Sealant	\$	21.23
	Belly To remove Belly Pan & Belly Insulation (Labor: 2 men x 2 days @ \$75 / hr.) - Add \$2,400.00 to 070000 NOTE: This will also allow you to review chassis condition & eliminate some rodent access points		DIY
	Thermal and Moisture Protection Total	\$	21.23

081316-	ALUMINUM DOORS Throughout		
	Remove & replace weather seals / gaskets on one (1) Entry Door & four (4) compartment doors (Materials Only)	\$	26.66
	<u>Curb-Side Compartment</u> To supply new lock	\$	40.00
	Rear Storage Compartment To remove existing, then supply & install two (2) replacement Metal Spring Latches + two (2) extra	\$	7.96
	Entry Door One (1) Deadbolt Lock (materials only) To install new Deadbolt Lock (2-5 hours) One (1) Door Striker Plate To supply & install new Entry Door Latch Stainless Steel	\$ \$ \$	21.75 330.00 8.00 8.90
	Aluminum Doors Tota	<b>I</b> \$	443.27
085113-	ALUMINUM WINDOWS Front / Center Window To supply new Rock Guard to replace existing	\$	399.95
	<u>Dinette</u> To reinstall one (1) Curb Side Window Latch Striker Plate		C/O
	Materials To install new window screen Aluminum window screen material Four (4) window pull handles Bug Seal	\$ \$ \$	DIY 24.00 48.00 33.31
	Aluminum Windows Tota	I \$	505.26
086000-	ROOF WINDOWS AND SKYLIGHTS		
	Vents Remove & replace screens for two (2) roof vents (Materials Only - DIY) Labor		PAID DIY
	Roof Windows and Skylights Tota	I <u>\$</u>	
087000-	HARDWARE ALLOWANCE	I <u>\$</u>	-
087000-			
087000-	HARDWARE ALLOWANCE		C/O N/C
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges		
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials	ı	N/C
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches	\$	N/C 34.07 49.65
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials  Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley	\$\$\$	N/C 34.07 49.65 TBD
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley To supply & install one (1) Roof Locker Latch  Bathroom	\$\$\$	N/C 34.07 49.65 TBD 5.90
087000-	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley To supply & install one (1) Roof Locker Latch  Bathroom Two (2) White Plastic Cabinet Latches (#18669) for overhead cabinets  Materials Four (4) 2" Narrow Hinges Nuts & Bolts	\$\$ \$ \$ \$\$	N/C 34.07 49.65 TBD 5.90 42.90
	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley To supply & install one (1) Roof Locker Latch  Bathroom Two (2) White Plastic Cabinet Latches (#18669) for overhead cabinets  Materials Four (4) 2" Narrow Hinges Nuts & Bolts One (1) Box of 100 Stainless Steel Screws  Cabinet Hardware Tota  GLAZING  Dinette Remove existing fasteners to remove the Street-side stack window & frame. Take the broken plexiglass out of the frame along with the vinyl	\$\$ \$ \$ \$\$\$	N/C  34.07 49.65 TBD  5.90  42.90  11.07 1.38 9.01  153.98
	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE  Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley To supply & install one (1) Roof Locker Latch  Bathroom Two (2) White Plastic Cabinet Latches (#18669) for overhead cabinets  Materials Four (4) 2" Narrow Hinges Nuts & Bolts One (1) Box of 100 Stainless Steel Screws  Cabinet Hardware Tota  GLAZING Dinette Remove existing fasteners to remove the Street-side stack window & frame. Take the broken plexiglass out of the frame along with the vinyl gasket To install a piece of 3/16" thick tempered glass to fit in the frame & bond the glass in the frame with silicone	\$\$ \$ \$ \$\$\$\$ \$	N/C  34.07 49.65 TBD  5.90  42.90  11.07 1.38 9.01  153.98
	HARDWARE ALLOWANCE  CABINET HARDWARE ALLOWANCE Dinette & Gaucho To replace Four (4) Dinette Bulkhead Storage Hinges To repair / replace three (3) under-seat drawer doors (Labor Only)  Materials Nine (9) pairs of hinges Twelve (12) Roller Catches Thirty two (32) LF' of Aluminum 3/8" U-channel Edge Banding  Galley To supply & install one (1) Roof Locker Latch  Bathroom Two (2) White Plastic Cabinet Latches (#18669) for overhead cabinets  Materials Four (4) 2" Narrow Hinges Nuts & Bolts One (1) Box of 100 Stainless Steel Screws  Cabinet Hardware Tota  GLAZING Dinette Remove existing fasteners to remove the Street-side stack window & frame. Take the broken plexiglass out of the frame along with the vinyl gasket To install a piece of 3/16" thick tempered glass to fit in the frame & bond	\$\$ \$ \$ \$\$\$\$ Z	N/C  34.07 49.65 TBD  5.90  42.90  11.07 1.38 9.01  153.98

088300-	MIRRORS		
	Bathroom Replace 8" x 48", 1/8" thick Mirror with Polished Edges	\$	32.66
	Mirrors Total	\$	32.66
	HARDWARE RESTORATION ALLOWANCE		
	Spare Tire Holder Remove rust & replace hardware as needed		C/O
	License Plate Holder		
	Screws & nuts for license plate	\$	1.31
	<u>Dining / Bathroom</u> To remove rust, prime, paint & lubricate Floor Vent Covers To sandblast and re-coat Stovetop Trivets		TBD TBD
	Hardware Restoration Total	\$	1.31
104000-	SAFETY SPECIALTIES ALLOWANCE		
	Emergency Gear Two (2) Warning Triangles	\$	15.00
	One (1) Kidde FA110 Multi Purpose Fire Extinguisher 1A10BC, 1 Pack	\$	21.70
	Three (3) First Alert 9.1.1 LED Emergency Beacon Flares with Storage Bag	\$	24.95
	Safety Specialties Total	\$	61.65
105700-	WARDROBE AND CLOSET SPECIALTIES		
	Galley Supply & install one (1) White Plastic Cabinet Latch (#18669) for Street		
	Side Closet	\$	21.45
	Wardrobe and Closet Specialties Total	\$	21.45
114000-	FOODSERVICE EQUIPMENT		
	Gas Refrigerator Diagnosis / Repair Stove / Oven Diagnosis / Repair		TBD TBD
	Foodservice Equipment Total	\$	-
122200-	WINDOW TREATMENTS		
	Throughout Curtain Material	П	ONATED
	Fabrication	\$	688.95
	Hardware Shipping		CLUDED
	Installation		DIY
	Window Treatments Total	\$	688.95
125219-	UPHOLSTERED SEATING ALLOWANCE		
	<u>Dining / Gaucho</u> Samples	\$	6.95
	Leather (Material Only)	\$	125.00
	Cloth for Cushions / Pillows (Material Only)	\$	360.76
	Nine-and-a-half (9.5) Yards of Tweed backing material (100% Polyolefin) Oeko-Tex Certified 100% Natural Dunlop Latex Extra Firm Cores,	IN	CLUDED
	UNCUT. (Includes Shipping) Three-and-a-Half (3.5) Yards of 24 oz., 1/4" J Mish Natural Performance	\$	1,756.00
	Wool Cushion / Padding Material (Includes Shipping)	\$	74.33
	Thirteen (13) Linear Yards Organic Cotton Ticking (includes Shipping) Fifteen (15) Yards 100% Natural Wool Batting (includes Shipping) [HAD	\$	252.95
	TO PURCHASE 20 YD. ROLL]	\$	910.80
	Fabrication Hardware	\$ \$	1,200.00 26.25
	Installation  NOTE: See Alternates #2 below to include Pillows		DIY
	Upholstered Seating Total	\$	4,713.04
	•		
224000-	PLUMBING FIXTURES AND FITTINGS To Be Determined		
	Plumbing Fixtures and Fittings Total		

C/O

	HVAC Tota	ıl \$	-
231000-	FACILITY FUEL SYSTEMS To supply two (2) 30 lb. / 7.1 gallon Worthington LP Tanks Shipping	\$ \$	100.00 50.00
	One (1) Cavagna Two-Tank Automatic Changeover Regulator Two (2) Stainless Steel Overbraided Propane Pigtails 24"	\$ \$	49.99 35.98
	Shipping To install two (2) Propane Tanks / System Installation (2 days labor) System assessment / certification	\$	N/A C/O 150.00
	Facility Fuel Systems Tota	ıl \$	385.97
260000-	ELECTRICAL ALLOWANCE		
	Throughout To supply one (1) Progressive Dynamics PD9260: 60 Amp Converter /		
	Battery Charger	\$	204.99
	To supply one (1) 12-Volt Fuse Box To install Amp Converter & 12-Volt Fuse Box	\$ \$	37.00 583.55
	Exterior		
	To supply new 7-way end plugs (Tow vehicle to Trailer)	\$	23.85
	To supply & install one (1) 12-volt / 7-pin inlet / socket w/ cover 7-pin Connector Burnishing Tool & DeOxIT (Materials Only)	\$ \$	103.96 15.00
	Electrical Tota	ıl \$	968.35
265100-	INTERIOR LIGHTING		
	Galley One (1) 6-3/4" Light Diffuser Square	\$	19.50
	Three (3) Frosted Light Bulbs One (1) Sink Light Diagnosis / Repair	\$	4.68 C/O
	( )		0/0
	<u>Throughout</u> Ten (10) 12V Bulbs (Frosted) [SPARES]	\$	15.99
	Interior Lighting Tota	ı <b>l</b> \$	24.18
265600-	EXTERIOR LIGHTING ALLOWANCE Rear Tune (2) 4 4 (8) Clear Signal Leges	\$	11 00
	Two (2) 4-1/8" Clear Signal Lenses	Ф	11.90
	Street Side One (1) Oval 1960's Marker Lens (Amber)	\$	4.39
	Three (3) Oval 1960's Marker Lens (Amber)	\$	13.17
	Exterior Lighting Total	\$	29.46
	0.1557/		
280000-	SAFETY AND SECURITY ALLOWANCE Sway Control Hitch		
	Hensley Arrow Sway Control Hitch Hensley Arrow Lifetime Warranty	\$ \$	750.00 517.00
	Remove rust & re-paint (Materials Only)	\$	35.36
	Install / adjust hitch		DIY
	Hitch Coupler Lock California Immobilizer	D	ONATED
	Gas Detection and Alarm		
	To supply & install one (1) Kidde Battery-Operated Combination Smoke/Carbon Monoxide Alarm with Voice Warning KN-COSM-BA	\$	25.57
	Safety and Security Total	<b>I</b> \$	1,327.93
407000	WASTEWATER HANDLING & TREATMENT		
46/000-	WASTEWATER HANDLING & TREATMENT To Be Determined		
	Wastewater Handling & Treatment Tota	ıl	

TOTAL \$ 18,649.25